

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	(strain load pressure force stress) near3 (gage gauge sens \$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (around) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:37
L2	2	(strain temperature incremental load pressure force stress) near3 (gage gauge sens \$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (around) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:38
L3	12	(strain temperature incremental load pressure force stress) near3 (gage gauge sens \$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (extend\$4 placed situated located direction disposed placing) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:39
L4	3	3 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:40

L5	0	4 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:40
L6	4	3 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:40
L7	4	6 and (radial\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:42
L8	79	(strain temperature incremental load pressure force stress) near3 (gage gauge sens \$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:45
L9	1	(strain temperature incremental load pressure force stress) near3 (gage gauge sens \$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (distribut\$4) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:45
L10	29	8 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:45

L11	7	10 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:46
L12	1	(strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (distribut\$4) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:53
L13	11	(strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (distribut\$4 located situated placed disposed directed direction) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:54
L14	2	13 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:55
L15	4	13 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:55

L16	103	(strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:59
L17	27	16 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:59
L18	9	17 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 18:59
L19	49	(plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (spaced separated displaced located situated distribut \$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:01
L20	6	19 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:01

L21	13	19 and (shaft)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:06
L22	3	21 and (flange)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:08
L23	382	73/774.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:10
L24	1	23 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (spaced separated displaced located situated distribut \$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:11
L25	232936	"73"/\$6.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:12

L26	23	25 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (spaced separated displaced located situated distribut \$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:12
L27	24	25 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (spaced separated displaced located situated distribut \$4 placed placing)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:12
L28	1	23 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:12

		(radial\$4) near3 (spaced separated displaced located situated distribut \$4 placed placing)				
L29	6	(plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (housing casing frame).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:15
L30	40	"5015926"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:17
L31	107946	"318"/\$6.ccIs.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:18
L32	0	31 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:18

L33	2	31 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:19
L34	6	"6026711"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:19
L35	0	34 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:20
L36	7	"6066907"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:20
L37	28	"6066907" "4724711"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:21

L38	1	37 and (plural\$4 multiple couple two second pair array) near3 (strain temperature incremental load pressure force stress) near3 (cell gage gauge sens\$4 detect\$4 transducer measur\$4) near3 (radial\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/28 19:21
-----	---	---	--	----	----	------------------

3/ 28/ 09 7:21:40 PM